

Asbestos Registry Submission Form

Facility Group:	Healthcare		
Facility Group Name:	Sun Country Regional Health Authority		
Facility Name:	Bengough Health Centre		
Street Address:	400 - 2nd Street West		
City:	Bengough, SK		
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email
Date Submitted:	July 19, 2017		

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Vinyl Asbestos Tile	Vinyl asbestos floor tile was identified throughout the facility. All 9"x9" vinyl floor tile throughout the facility shall be considered asbestos-containing until the material is determined to be asbestos free.	The vinyl floor tile contains 1-5% Chrysotile Asbestos and is considered a non-friable asbestos material. The floor tiles are in the form of 9"x9" tiles located throughout the facility.	Low. The asbestos is imbedded in the floor tile resin.	A non-friable product is one that can not be crumbled or reduced to powder or smaller fragments by hand pressure.
Sheet Vinyl Floor	Asbestos-containing sheet vinyl floor was identified within the following areas of the facility: Basement Corridor C05, Basement Rooms 1 -3, Main Floor Rooms 11 - 35, 37 & 42 and the Main Floor Corridor.	The sheet vinyl floor contains 30% Chrysotile Asbestos and is considered a friable asbestos material. The flooring is identifiable by the dark brown pattern.	Low. The asbestos is present within the felt backing beneath the surface of the flooring.	Ensure the facing surface of the sheet flooring is maintained in good repair. APEC removed the sheet flooring from the Laundry Room in November 2014.
Pipefitting Compound	Asbestos pipefitting compound was identified throughout the Crawlspace as well as the following areas: Laundry Room, Sprinkler Room and the Boiler Room. All pipefitting compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The pipefitting compound contains 30 - 50% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass. Much of this material is located within ceiling spaces and majority of access is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand. All accessible pipefitting compound was repaired / removed by APEC in November 2014.
Transite Pipe	Asbestos-containing transite pipe was identified within Crawlspace #3. All transite pipe located within the facility shall be considered asbestos-containing until the material is determined to be asbestos free.	The transite pipe contains 40% Chrysotile Asbestos and is considered a non-friable asbestos material.	Low. Access to this area is restricted to Maintenance personnel.	A non-friable product is one that can not be crumbled or reduced to powder or smaller fragments by hand pressure.
Drywall Mud Compound	Asbestos Containing Drywall Mud Compound was identified in compilation samples taken from the main floor in various locations. Asbestos containing drywall mud compound is mostly located on joints, tape seams, and screw holes. It is advised that all drywall mud compound in the facility be considered asbestos containing until sampling proves otherwise.	Drywall Mud Compound contains 1-5% Chrysotile and is considered a friable product.	Low. The asbestos is imbedded in the mud at joints, tape seams, and screw holes.	A friable product is one that is easily crumbled by hand pressure.
Ceiling Tile	Asbestos Containing Ceiling Tile was identified in the main corridor of the building. Any ceiling tile matching the tile in the main corridor should be considered asbestos containing. It is recommended that any other ceiling tile patterns in the facility be considered asbestos containing until sampling proves otherwise.	Ceiling Tile contains 1-5% Chrysotile and is considered a friable product.	Low. The asbestos is imbedded in the resin of the ceiling tile.	A friable product is one that is easily crumbled by hand pressure.