

Asbestos Registry Submission Form

Facility Group:	Healthcare		
Facility Group Name:	Sun Country Regional Health Authority		
Facility Name:	Carnduff Sunset Haven		
Street Address:	415 Spencer Street		
City:	Carnduff, SK		
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email
Date Submitted:	July 19, 2017		

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Sheet Vinyl Floor	Asbestos-containing sheet vinyl floor was identified within the following areas of the facility: Resident rooms # 1 - 4, 6 -8 & 15. Also located within the Housekeeping Room, the Med Room, the Clean Utility area and the Resident room across the corridor from Room 24.	The sheet vinyl floor contains 30% Chrysotile Asbestos and is considered a friable asbestos material. The flooring is identifiable by the large irregular stone pattern.	Low. The asbestos is present within the felt backing beneath the surface of the flooring.	Ensure the facing surface of the sheet flooring is maintained in good repair.
Asbestos Debris	Located throughout the Crawlspace.	Loose asbestos debris, a product of deteriorating mechanical insulation located throughout the Crawlspace. The debris was found to contain 60 - 70% chrysotile asbestos and is considered to be friable.	Low. Restricted to Maintenance Staff equipped with proper PPE.	Crawlspace was abated in June 2013 by Associated Asbestos Abatement Ltd.
Firestop Material	The firestop material was identified at wall/ceiling penetrations within Basement Panel Room. All firestop mud compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The firestop contains 60% Chrysotile Asbestos and is considered a friable asbestos material. Firestop material includes all mud compound sealing off any wall/ceiling penetrations within the facility.	Low to Moderate. Restricted to maintenance personnel.	All damaged firestop material was repaired / removed from the Panel Room in June 2013 by Associated Asbestos Abatement.
Duct Expansion Canvass	Asbestos duct expansion canvass was identified in the Basement Maintenance Shop. All duct expansion canvass shall be considered asbestos-containing until the material is determined to be asbestos free.	The duct expansion canvass was found to contain 30-40% Chrysotile Asbestos and are considered a friable asbestos material.	Low. Access is restricted to maintenance personnel only	A friable product is one that is easily crumbled by hand pressure.
Heat Deflector Shield	Asbestos heat deflector shield material was found in the light fixtures located in Housekeeping Rooms #1 & #1. All heat shield material shall be considered asbestos-containing until the material is determined to be asbestos free.	The heat deflector shield material contains 80% Chrysotile Asbestos and is considered a friable asbestos material. The heat deflector shields are located in the old Incandescent light fixtures in the rooms identified.	Low. Access to this area is restricted to Maintenance personnel.	A friable product is one that is easily crumbled by hand pressure.
Lineal Pipe Insulation	Asbestos lineal pipe insulation was identified in various areas of the Basement including: the Maintenance Shop, the Storage / Sink room, the Panel room and the Pump room. All Lineal Pipe Insulation shall be considered asbestos-containing until the material is determined to be asbestos free.	The lineal insulation contains 70% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass. Access is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand. All accessible lineal pipe insulation was repaired / removed by Associated Asbestos Abatement in June 2013.
Pipefitting Compound	Asbestos pipefitting compound was identified in the Crawlspace and various areas of the Basement including: the Maintenance Shop, the Storage / Sink room, the Panel room and the Pump room. All pipefitting compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The pipefitting compound contains 10 - 60% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass. Access is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand. All accessible pipefitting compound was repaired / removed by Associated Asbestos Abatement in June 2013.
Drywall Mud Compound	Asbestos Containing Drywall Mud Compound was identified in compilation sample taken from the main entry to the facility. Asbestos containing drywall mud compound is mostly located on joints, tape seams, and screw holes. It is advised that all drywall mud compound in the facility be considered asbestos containing until sampling proves otherwise.	Drywall Mud Compound contains 1-5% Chrysotile and is considered a friable product.	Low. The asbestos is imbedded in the mud at joints, tape seams, and screw holes.	A friable product is one that is easily crumbled by hand pressure.