

Asbestos Registry Submission Form

Facility Group:	Healthcare			
Facility Group Name:	Sun Country Regional Health Authority			
Facility Name:	Estevan Regional Nursing Home			
Street Address:	1921 Wellock Road			
City:	Estevan, SK			
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir	
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager	
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca	
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377	
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email	
Date Submitted:	July 19, 2017			

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Asbestos Debris	Located throughout the Kitchen Crawlspace.	Loose asbestos debris, a product of deteriorating mechanical insulation located throughout the Crawlspace. The debris was found to contain 70% chrysotile asbestos and is considered to be friable.	Low. Restricted to Maintenance Staff equipped with proper PPE.	Crawlspace was abated in November 2014 by APEC.
Pipefitting Compound	Asbestos pipefitting compound was identified in the Crawlspace and various areas of the Basement including: the Boiler Room, Stairwell, Corridor, Laundry Room, Maintenance Office, Storage Room and Washrooms . All pipefitting compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The pipefitting compound contains 15 - 75% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass. Access is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand. All accessible pipefitting compound was repaired / removed by Associated Asbestos Abatement in June 2013.
Boiler Breaching	Asbestos boiler breaching was found in Boiler Room. All breaching shall be considered asbestos-containing until the material is determined to be asbestos free.	The breaching insulation contains 50% Chrysotile / Amosite Asbestos and is considered a friable asbestos material.	Low. Access to this area is restricted to Maintenance personnel.	A friable product is one that is easily crumbled by hand pressure.
Drywall Mud Compound	Asbestos Containing Drywall Mud Compound was identified in compilation samples taken from the basement stairwell. Asbestos containing drywall mud compound is mostly located on joints, tape seams, and screw holes. It is advised that all drywall mud compound in the facility be considered asbestos containing until sampling proves otherwise.	Drywall Mud Compound contains 1-5% Chrysotile and is considered a friable product.	Low. The asbestos is imbedded in the mud at joints, tape seams, and screw holes.	A friable product is one that is easily crumbled by hand pressure.