

Type of Facility:	Health Care Facility		
Facility Group Name:	Sun Country Health Authority		
Facility Name:	Arcola Health Centre		
Location:	607 Prairie Avenue, Arcola, SK		
Date of Submission:	31-Dec-18		
Primary Contact Name:	Marlon Milbrandt		
Primary Contact Title:	Director - Building Services Rural	Secondary Contact Name:	John Megenbir
Primary Contact Email Address:	Marlon.Milbrandt@saskhealthauthority.ca	Secondary Contact Title:	Building Services Manager
Primary Contact Telephone:	(306) 786-0416	Secondary Contact Email Address:	John.Megenbir@saskhealthauthority.ca
Primary Contact Preferred Method:	Email	Secondary Contact Telephone:	306-842-8377
		Secondary Contact Preferred Method:	Email

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Ceiling Tile	The asbestos-containing Ceiling Tile was identified within the following areas of the facility: Corridor 104.	The Ceiling Tile contains 1-5% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Drywall Mud Compound	The asbestos-containing Drywall Mud Compound was identified in the following areas of the facility: Basement, Rm 106 Reception and Patient Wing. Compilation samples were taken from various locations. Consider all Drywall Mud Compound to be asbestos-containing until further testing proves otherwise.	The Drywall Mud Compound contains 1-5% Chrysotile asbestos and is considered a non-friable asbestos material. Drywall Mud Compound is located at drywall seams/joints and nail/screw holes throughout the facility.	High	A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.
Fire Door Interior Liner	The asbestos-containing Fire Door Interior Liner was identified in the following areas of the facility: Mechanical Room B10.	The Fire Door Interior Liner contains 60% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Gasket Material	The asbestos-containing Gasket Material was identified in the following areas of the facility: Mechanical Room B10	The Gasket Material contains 45% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Heat Deflector Shield	The asbestos-containing Heat Deflector Shields were identified within the following areas within the facility: B17 Staff Lounge, B19 Men's Washroom, B20 Change Room, B21 Women's Washroom, 129 O.R and 132 Case Room.	The Heat Deflector Shields contain 60% Chrysotile asbestos are considered a friable asbestos material. The Heat Shield is located directly above the light bulbs within the light fixture to prevent overheating of building materials above.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure. Ensure the globe of the light fixture is in place to enclose/conceal the Heat Deflector Shield.
Lineal Pipe Insulation	The asbestos-containing Lineal Pipe Insulation was identified within the following areas of the facility: B09 and B15 Corridors.	The Lineal Pipe Insulation contains 70% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by had pressure.
Mud Compound	The asbestos-containing Mud Compound was identified within the following areas of facility: B10 Mechanical Room.	The Mud Compound contains 40% Chrysotile asbestos and is considered a friable material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Sheet Flooring	The asbestos-containing Sheet Flooring was identified within the following areas of the facility: 135 Surgical Storage, 141 Corridor, 143 Soiled Linen, 144 Storage, 145 Clean Utility, 146 Soiled Utility, Ward 1-8, Ward Wash 3/5/7 and Quiet Room.	The Sheet flooring contains 40% Chrysotile asbestos and is considered a friable asbestos material. The sheet flooring was found in a variety of colours and patterns throughout the facility.	High	The asbestos is present within the felt backing beneath the surface of the flooring. A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Vinyl Floor Tile	The asbestos-containing Vinyl Floor Tile was identified within the following areas of the facility: B09/B15 Corridor, B12 Kitchen Storage, B16 D.W, B17 Staff Lounge, B18 Change Room, and S03 Stairwell.	The Vinyl Floor Tile contains 1-5% Chrysotile asbestos and is considered a non-friable asbestos material. The floor tiles are found in a variety of colours and patterns throughout the facility.	Low	The asbestos is embedded in the resin of the floor tile. Although the floor tile is labelled high accessibility to the public, there is no hazard. A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.