

# Asbestos Registry Submission Form

<b>Facility Group:</b>	Healthcare	<b>Secondary Contact Name:</b>	John Megenbir
<b>Facility Group Name:</b>	Sun Country Regional Health Authority	<b>Secondary Contact Title:</b>	Maintenance Manager
<b>Facility Name:</b>	Kipling Memorial Health Centre	<b>Secondary Contact Email Address:</b>	John.Megenbir@schr.sk.ca
<b>Street Address:</b>	Kipling, SK	<b>Secondary Contact Telephone:</b>	306-842-8377
<b>City:</b>	Kipling, SK	<b>Secondary Contact Preferred Method:</b>	Email
<b>Primary Contact Name:</b>	Sam Baison		
<b>Primary Contact Title:</b>	Director - Physical Plant		
<b>Primary Contact Email Address:</b>	Samuel.Baison@schr.sk.ca		
<b>Primary Contact Telephone:</b>	306-842-8304		
<b>Primary Contact Preferred Method:</b>	Email		
<b>Date Submitted:</b>	June 30, 2016		

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Vinyl Asbestos Tile	The vinyl asbestos tile was identified throughout much of the Basement and Main Floor of the facility. All 9"x9" vinyl floor tile throughout the facility shall be considered asbestos-containing until the material is determined to be asbestos free.	The vinyl floor tile contains 1-5% Chrysotile Asbestos and is considered a non-friable asbestos material. The floor tiles are in the form of 9"x9" tiles.	Low. The asbestos is imbedded in the floor tile resin.	A non-friable product is one that can not be crumbled or reduced to powder or smaller fragments by hand pressure.
Sheet Vinyl Floor	Asbestos-containing sheet vinyl floor was identified throughout much of the Basement and Main Level of the facility.	The sheet vinyl floor contains 30% Chrysotile Asbestos and is considered a friable asbestos material. The sheet floor is identifiable by the brown with orange and white fleck patterns.	Low. The asbestos is present within the felt backing beneath the surface of the flooring.	Ensure the facing surface of the sheet flooring is maintained in good repair.
Firestop Material	Asbestos firestop material was identified at ceiling penetrations located in the ceiling space of Rooms 203, 207, 223 as well as the Crawlspace. All firestop mud compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The firestop contains 50-70% Chrysotile Asbestos and is considered a friable asbestos material. Firestop material includes all mud compound sealing off any wall/ceiling penetrations within the facility.	Low to Moderate. Restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand.
Heat Deflector Shield	Asbestos heat deflector shield material was found in the light fixtures located in Rooms 106, 109, 115 and 215. All heat shield material shall be considered asbestos-containing until the material is determined to be asbestos free.	The heat deflector shield material contains 70% Chrysotile Asbestos and is considered a friable asbestos material. The heat deflector shields are located in the old Incandescent light fixtures in the rooms identified.	Low. Access to this area is restricted to Maintenance personnel.	A friable product is one that is easily crumbled by hand pressure.
Lineal Pipe Insulation	Asbestos lineal pipe insulation was identified in various areas of the Basement. All Lineal Pipe Insulation shall be considered asbestos-containing until the material is determined to be asbestos free.	The lineal insulation contains 75% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass.	A friable product is one that is easily crumbled by hand.
Pipefitting Compound	Asbestos pipefitting compound was identified throughout the Basement. All pipefitting compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The pipefitting compound contains 20-70% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass.	A friable product is one that is easily crumbled by hand.