

Asbestos Registry Submission Form

Facility Group:	Healthcare		
Facility Group Name:	Sun Country Regional Health Authority		
Facility Name:	Weyburn General Hospital		
Street Address:	201 - 1st Avenue NE		
City:	Weyburn, SK		
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email
Date Submitted:	June 30, 2016		

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Vinyl Asbestos Tile	Vinyl asbestos floor tile was identified throughout the facility. All 9"x9" vinyl floor tile throughout the facility shall be considered asbestos-containing until the material is determined to be asbestos free.	The vinyl floor tile contains 1-5% Chrysotile Asbestos and is considered a non-friable asbestos material. The floor tiles are in the form of 9"x9" tiles located throughout the facility.	Low. The asbestos is imbedded in the floor tile resin.	A non-friable product is one that can not be crumbled or reduced to powder or smaller fragments by hand pressure.
Heat Deflector Shield	Asbestos heat deflector shield material was identified within in the following areas: 215.3 Linen, 226 OR, 235 Day Surgery Recovery, 253.1 Washroom, 258.1 Washroom, 260.1 Washroom, 502-2 & 3 Stairwells. All heat shield material shall be considered asbestos-containing until the material is determined to be asbestos free.	The heat deflector shield material contains 60% Chrysotile Asbestos and is considered a friable asbestos material. The heat deflector shields are located in the old incandescent light fixtures in the rooms identified.	Low. Access to this area is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand pressure.
Transite Wallboard	Asbestos transite wallboard was identified within the Penthouse Mechanical Room 414. All transite wallboard located within the facility shall be considered asbestos-containing until the material is determined to be asbestos free.	The transite wallboard contains 60% Chrysotile Asbestos and is considered a non-friable asbestos material.	Low. Access to this area is restricted to maintenance personnel.	A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.
Duct Insulation	Asbestos duct insulation was identified within the Boiler Room 048 as well as Penthouse Mechanical Room 414. The insulation is enclosed with canvass. All Mud Compound on shall be considered asbestos-containing until the material is determined to be asbestos free.	The Mud Compound contains 60-70% Chrysotile Asbestos and is considered a friable asbestos material. The Mud Compound is located on the ducting beneath a layer of canvass.	Low. Access to this area is restricted to maintenance personnel.	All accessible asbestos duct insulation was removed from Boiler Room 048 and all necessary repairs were made in Penthouse Mechanical Room 414 in December 2013 by APEC.
Firestop Material	Asbestos firestop material was identified at the wall penetrations within Boiler Room 048 leading into Corridor OC47. All firestop mud compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The firestop contains 30% Chrysotile Asbestos and is considered a friable asbestos material. Firestop material includes all mud compound sealing off any wall/ceiling penetrations within the facility.	Low to Moderate. Restricted to maintenance personnel.	All firestop material was repaired / removed from the Boiler Room in December 2013 by APEC.
Boiler Insulation	Asbestos boiler insulation was identified within Boiler Room 048. The insulation is enclosed with metal cladding. All insulation located on the boilers shall be considered asbestos-containing until the material is determined to be asbestos free.	The Mud Compound contains 60-70% Chrysotile Asbestos and is considered a friable asbestos material. The Mud Compound is located on the ducting beneath a layer of canvass.	Low. Access to this area is restricted to maintenance personnel.	The insulation is only accessible around the service ports on the sides of the boilers. The area around each service port was sealed in December 2013 by APEC.
Lineal Pipe Insulation	Asbestos lineal pipe insulation was identified in various areas throughout the facility. All Lineal Pipe Insulation shall be considered asbestos-containing until the material is determined to be asbestos free.	The lineal insulation contains 60-70% Chrysotile Asbestos. The insulation is considered a friable material.	Low - Moderate. Enclosed with canvass.	A friable product is one that is easily crumbled by hand. All accessible lineal pipe insulation was repaired / removed by APEC in December 2013.
Pipefitting Compound	Asbestos pipefitting compound was identified throughout the facility. All pipefitting compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The pipefitting compound contains 30 - 60% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass. Much of this material is located within ceiling spaces and majority of access is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand. All accessible pipefitting compound was repaired / removed by APEC in December 2013.