

Asbestos Registry Submission Form

Facility Group:	Healthcare			
Facility Group Name:	Sun Country Regional Health Authority			
Facility Name:	Carlyle Moose Mountain Lodge			
Street Address:	801 Souris Avenue			
City:	Carlyle, SK			
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir	
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager	
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca	
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377	
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email	
Date Submitted:	June 30, 2016			

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Sheet Vinyl Floor	Asbestos-containing sheet vinyl floor was identified within the following areas of the facility: Resident / Storage Rooms #1 thru #36 as well as the Storage Room adjacent Room #25.	The sheet vinyl floor contains 40% Chrysotile Asbestos and is considered a friable asbestos material.	Low. The asbestos is present within the felt backing beneath the surface of the flooring.	Ensure the facing surface of the sheet flooring is maintained in good repair.
Vermiculite	Vermiculite was identified within the attic of the facility. All attic spaces shall be assumed to contain asbestos-containing vermiculite insulation.	The Vermiculite contains >0.1% Actinolite asbestos and is considered a friable asbestos material. This material is characteristically used as a loose fill insulation in attics.	Low. The vermiculite is located within the Attic of the facility.	A friable product is one that can be crumbled or reduced to powder or small fragments by hand pressure. Due to this materials location, the potential for disturbance is low and access is limited to Maintenance Staff.
