

# Asbestos Registry Submission Form

<b>Facility Group:</b>	Healthcare			
<b>Facility Group Name:</b>	Sun Country Regional Health Authority			
<b>Facility Name:</b>	Kipling Willowdale Lodge			
<b>Street Address:</b>	128 - 4th Street South			
<b>City:</b>	Kipling, SK			
<b>Primary Contact Name:</b>	Sam Baison	<b>Secondary Contact Name:</b>	John Megenbir	
<b>Primary Contact Title:</b>	Director - Physical Plant	<b>Secondary Contact Title:</b>	Maintenance Manager	
<b>Primary Contact Email Address:</b>	Samuel.Baison@schr.sk.ca	<b>Secondary Contact Email Address:</b>	John.Megenbir@schr.sk.ca	
<b>Primary Contact Telephone:</b>	306-842-8304	<b>Secondary Contact Telephone:</b>	306-842-8377	
<b>Primary Contact Preferred Method:</b>	Email	<b>Secondary Contact Preferred Method:</b>	Email	
<b>Date Submitted:</b>	July 19, 2017			

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Pipefitting Compound	Asbestos pipefitting compound was identified in the Crawlspace as well as Rooms 1-4 in the Basement. All pipefitting compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The pipefitting compound contains 20-30% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass.	A friable product is one that is easily crumbled by hand.
Sheet Vinyl Floor	Asbestos-containing sheet vinyl floor was identified within the following areas of the facility: Basement Corridor as well Basement Rooms 1-3. Also located on the Main Floor in Rooms 5, 10-21, 30-41, East & West Corridors, 44 and 55-57.	The sheet vinyl floor contains 30-35% Chrysotile Asbestos and is considered a friable asbestos material. The flooring is identifiable by the large brown/tan stone pattern.	Low. The asbestos is present within the felt backing beneath the surface of the flooring.	Ensure the facing surface of the sheet flooring is maintained in good repair.