

# Asbestos Registry Submission Form

<b>Facility Group:</b>	Healthcare		
<b>Facility Group Name:</b>	Sun Country Regional Health Authority		
<b>Facility Name:</b>	Wawota Memorial Health Centre		
<b>Street Address:</b>	Choo Foo Crescent		
<b>City:</b>	Wawota, SK		
<b>Primary Contact Name:</b>	Sam Baison	<b>Secondary Contact Name:</b>	John Megenbir
<b>Primary Contact Title:</b>	Director - Physical Plant	<b>Secondary Contact Title:</b>	Maintenance Manager
<b>Primary Contact Email Address:</b>	Samuel.Baison@schr.sk.ca	<b>Secondary Contact Email Address:</b>	John.Megenbir@schr.sk.ca
<b>Primary Contact Telephone:</b>	306-842-8304	<b>Secondary Contact Telephone:</b>	306-842-8377
<b>Primary Contact Preferred Method:</b>	Email	<b>Secondary Contact Preferred Method:</b>	Email
<b>Date Submitted:</b>	July 19, 2017		

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Transite Pipe	Asbestos transite pipe was identified in the ceiling space of the Staff Room, the Staff Washroom and the Main Corridor. All transite pipe located within the facility shall be considered asbestos-containing until the material is determined to be asbestos free.	The transite pipe contains 30% Chrysotile Asbestos and is considered a non-friable asbestos material.	Low. Contained within the ceiling space. Accessible only by maintenance personnel.	A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.