

Type of Facility:	Health Care Facility		
Facility Group Name:	Sun Country Health Authority		
Facility Name:	Carlyle Community Health Services		
Location:	206 Railway Avenue East, Carlyle, SK		
Date of Submission:	31-Dec-18		
Primary Contact Name:	Marlon Milbrandt		
Primary Contact Title:	Director - Building Services Rural	Secondary Contact Name:	John Megenbir
Primary Contact Email Address:	Marlon.Milbrandt@saskhealthauthority.ca	Secondary Contact Title:	Building Services Manager
Primary Contact Telephone:	(306) 786-0416	Secondary Contact Email Address:	John.Megenbir@saskhealthauthority.ca
Primary Contact Preferred Method:	Email	Secondary Contact Telephone:	306-842-8377
		Secondary Contact Preferred Method:	Email

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Ceiling Tile	The asbestos-containing Ceiling Tile was identified within the following areas of the facility: Main Floor.	The Ceiling Tile contains 1-5% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Drywall Mud Compound	The asbestos-containing Drywall Mud Compound was identified in the following areas of the facility: Compilation samples were taken from various locations on the Main Floor. Consider all Drywall Mud Compound to be asbestos-containing until further testing proves otherwise.	The Drywall Mud Compound contains 1-5% Chrysotile asbestos and is considered a non-friable asbestos material. Drywall Mud Compound is located at drywall seams/joints and nail/screw holes throughout the facility.	High	A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.
Spray-Applied Fireproofing	The asbestos-containing Spray-Applied Fireproofing was identified within the exterior wall cavities and the underside of roof decking throughout the South Garage portion of the facility. In addition, similar material was identified on the interior side of the perimeter metal wall cladding and the underside of the exterior roof decking in the Front Public Health Office Area.	The Spray-Applied Fireproofing contains Crocidolite asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.