

Type of Facility:	Health Care Facility		
Facility Group Name:	Sun Country Health Authority		
Facility Name:	Estevan Regional Nursing Home		
Location:	1921 Wellock Road, Estevan, SK		
Date of Submission:	20-Dec-18		
Primary Contact Name:	Marlon Milbrandt	Secondary Contact Name:	John Megenbir
Primary Contact Title:	Director - Building Services Rural	Secondary Contact Title:	Building Services Manager
Primary Contact Email Address:	Marlon.Milbrandt@saskhealthauthority.ca	Secondary Contact Email Address:	John.Megenbir@saskhealthauthority.ca
Primary Contact Telephone:	(306) 786-0416	Secondary Contact Telephone:	(306) 842-8377
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Debris	The asbestos-containing Debris was identified within the following areas of the facility: Kitchen Crawlspace.	Asbestos-containing Debris contains 70% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Drywall Mud Compound	The asbestos-containing Drywall Mud Compound was identified in the following areas of the facility: Basement Stairwell. Consider all Drywall Mud Compound to be asbestos-containing until further testing proves otherwise.	The Drywall Mud Compound contains 1-5% Chrysotile asbestos and is considered a non-friable asbestos material. Drywall Mud Compound is located at drywall seams/joints and nail/screw holes throughout the facility.	High	A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.
Mud Compound	The asbestos-containing Mud Compound was identified within the following areas of facility: Boiler Room.	The Mud Compound contains 30% Chrysotile asbestos and 20% Amosite asbestos and is considered a friable material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Pipe Fitting Compound	The asbestos-containing Pipe Fitting Compound was identified within the following areas of the facility: A Wing, B Wing and C Wing Crawlspace, Boiler Room, Basement Stairwell, Basement Corridor, Basement Laundry Room, Basement Maintenance Office, Basement Storage Room, Basement Ladies Washroom and Basement Men's Washroom.	The Pipe Fitting Compound contains 15-75% Chrysotile asbestos and is considered a friable asbestos material. Pipe Fitting Compound includes all mud compound located on elbows, T's, hangers, and valves located on the mechanical piping throughout the facility.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.