

Type of Facility:	Health Care Facility		
Facility Group Name:	Sun Country Health Authority		
Facility Name:	Weyburn Special Care Home		
Location:	704 - 5th Street NE, Weyburn, SK		
Date of Submission:	31-Dec-18		
Primary Contact Name:	Marlon Milbrandt	Secondary Contact Name:	Barry Brumfield
Primary Contact Title:	Director - Building Services Rural	Secondary Contact Title:	Building Services Manager
Primary Contact Email Address:	Marlon.Milbrandt@saskhealthauthority.ca	Secondary Contact Email Address:	Barry.Brumfield@saskhealthauthority.ca
Primary Contact Telephone:	(306) 786-0416	Secondary Contact Telephone:	(306) 842-8316
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Heat Deflector Shield	The asbestos-containing Heat Deflector Shields were identified within the following areas within the facility: Corridor C01S, Storage 06S and Washroom 07S.	The Heat Deflector Shields contain 60% Chrysotile asbestos are considered a friable asbestos material. The Heat Shield is located directly above the light bulbs within the light fixture to prevent overheating of building materials above.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure. Ensure the globe of the light fixture is in place to enclose/conceal the Heat Deflector Shield.
Sheet Flooring	The asbestos-containing Sheet Flooring was identified within the following areas of the facility: Activity Room 148, Coffee Room 130, Clean Utility 160, Corridor C132/C146/C158/C159/C162/C163/C164, Dining Room 145, Dishwasher 148.1, Housekeeping 162.2, Library 131, Maintenance Office 147, Res Lavatory 61.1/62.1/63.1/64/65.1/66.1/67.1/68.1/69.1/70.1/71.1/72.1/73.1/74.1/75.1/76.1/77.1/78.1/79.1/80.1/81.1/82.1/83.1/84.1/85.1/86.1/87.1/88.1/89.1/90.1/91.1/92.1/93.1/94.1/95.1/96.1/97.1/98.1/99.1/100.1/101.1/102.1/103.1/104.1/105.1/106.1/107.1/108.1/109.1/110.1, Res Room 103/104/105/106/107/108/109/110, Service 132.1/148.3/151.4/151.5/151.6, Soiled Utility 161, Staff Locker 125, Staff Room 149, Stairwell S01-4/S01-5, Storage 132.2/148.2, Supply Room 155, Washroom 140.1/156 and Whirlpool 162.1.	The Sheet flooring contains 30% Chrysotile asbestos and is considered a friable asbestos material. The sheet flooring was found in a variety of colours and patterns throughout the facility.	High	The asbestos is present within the felt backing beneath the surface of the flooring. A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Transite Pipe	The asbestos-containing Transite Pipe was identified within the following areas of the facility: Crawlspace South.	The Transite Pipe contains 30% Chrysotile/Crocidolite asbestos and is considered a non-friable asbestos material.	Low	A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.