

Type of Facility:	Health Care Facility		
Facility Group Name:	Sun Country Health Authority		
Facility Name:	Bengough Health Centre		
Location:	400 - 2nd Street West, Bengough, SK		
Date of Submission:	30-Dec-19		
Primary Contact Name:	John Megenbir	Secondary Contact Name:	Marlon Milbrandt
Primary Contact Title:	Maintenance Manager	Secondary Contact Title:	Director - Building Services Rural
Primary Contact Email Address:	John.Megenbir@schr.sk.ca	Secondary Contact Email Address:	Marlon.Milbrandt@saskhealthauthority.ca
Primary Contact Telephone:	306-842-8377	Secondary Contact Telephone:	(306) 786-0416
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Asbestos Sheet Flooring	The asbestos-containing Sheet Flooring was identified within the following areas of the facility: Basement C05 Corridor, 01 Storage, 03 Sprinkler Room. Main Floor Resident Rooms 11-14, 16-21, 24-27, 29-31, 33-37, and 42. Main Floor Corridors 15-21 and 30-35.	The Sheet flooring contains 30% Chrysotile asbestos and is considered a friable asbestos material. The sheet flooring was found in a variety of colours and patterns throughout the facility.	High	The asbestos is present within the felt backing beneath the surface of the flooring. A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Ceiling Tile	The asbestos-containing Ceiling Tile was identified within the following areas of the facility: Main Floor Corridor.	The Ceiling Tile contains 1-5% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Drywall Mud Compound	The asbestos-containing Drywall Mud Compound was identified in the following areas of the facility: Compilation samples were taken from various locations on the Main Floor. Consider all Drywall Mud Compound to be asbestos-containing until further testing proves otherwise.	The Drywall Mud Compound contains 1-5% Chrysotile asbestos and is considered a non-friable asbestos material. Drywall Mud Compound is located at drywall seams/joints and nail/screw holes throughout the facility.	High	A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.
Pipe Fitting Compound	The asbestos-containing Pipe Fitting Compound was identified within the following areas of the facility: Crawlspace 4 and 6. Basement 02 Laundry, 03 Sprinkler Room, and 04 Boiler Room.	The Pipe Fitting Compound contains 30-50% Chrysotile asbestos and is considered a friable asbestos material. Pipe Fitting Compound includes all mud compound located on elbows, T's, hangers, and valves located on the mechanical piping throughout the facility.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Transite Pipe	The asbestos-containing Transite Pipe was identified within the following areas of the facility: Crawlspace 3.	The Transite Pipe contains 40% Chrysotile asbestos and is considered a non-friable asbestos material.	Low	A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.