

Type of Facility:	Health Care Facility		
Facility Group Name:	Sun Country Health Authority		
Facility Name:	Carnduff Sunset Haven		
Location:	415 Spencer Street, Carnduff, SK		
Date of Submission:	16-Dec-19		
Primary Contact Name:	John Megenbir	Secondary Contact Name:	Marlon Milbrandt
Primary Contact Title:	Building Services Manager	Secondary Contact Title:	Director - Building Services Rural
Primary Contact Email Address:	John.Megenbir@saskhealthauthority.ca	Secondary Contact Email Address:	Marlon.Milbrandt@saskhealthauthority.ca
Primary Contact Telephone:	(306) 842-8377	Secondary Contact Telephone:	(306) 786-0416
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Drywall Mud Compound	The asbestos-containing Drywall Mud Compound was identified in the following areas of the facility: Main Entrance. Consider all Drywall Mud Compound to be asbestos-containing until further testing proves otherwise.	The Drywall Mud Compound contains 2% Chrysotile asbestos and is considered a non-friable asbestos material. Drywall Mud Compound is located at drywall seams/joints and nail/screw holes throughout the facility.	High	A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.
Sheet Flooring	The asbestos-containing Sheet Flooring was identified within the following areas of the facility: Main Floor Resident Rooms 1-4, 6-8, and 15. North House Keeping, Med Room, Clean Utility and Resspir Room. Sheet vinyl floor was identified underneath the new flooring within the following areas of the facility: Resident rooms # 9 - 14, 16 - 23, and 24 - 26.	The Sheet flooring contains 30% Chrysotile asbestos and is considered a friable asbestos material. The sheet flooring was found in a variety of colours and patterns throughout the facility.	High	The asbestos is present within the felt backing beneath the surface of the flooring. A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Gasket Material	The asbestos-containing Gasket Material was identified in the following areas of the facility: Maintenance Shop.	The Gasket Material contains 30-40% Chrysotile asbestos and is considered a friable asbestos material. The Gasket Material is located on the duct in the maintenance shop.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Asbestos Debris	Located throughout the main crawlspace and kitchen crawlspace.	Loose asbestos debris, a product of deteriorating mechanical insulation located throughout the Crawlspace. The debris was found to contain 60 - 70% chrysotile asbestos and is considered to be friable.	Low. Restricted to Maintenance Staff equipped with proper PPE.	Crawlspace was abated in June 2013 by Associated Asbestos Abatement Ltd.