

Type of Facility:	Health Care Facility		
Facility Group Name:	Sun Country Health Authority		
Facility Name:	Weyburn Community Health Services Building		
Location:	900 Saskatchewan Drive, Weyburn, SK		
Date of Submission:	30-Dec-19		
Primary Contact Name:	John Megenbir	Secondary Contact Name:	Marlon Milbrandt
Primary Contact Title:	Maintenance Manager	Secondary Contact Title:	Director - Building Services Rural
Primary Contact Email Address:	John.Megenbir@schr.sk.ca	Secondary Contact Email Address:	Marlon.Milbrandt@saskhealthauthority.ca
Primary Contact Telephone:	306-842-8377	Secondary Contact Telephone:	(306) 786-0416
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Ceiling Texture	The asbestos-containing Ceiling Texture was identified within the following areas of the facility: C102 Corridor.	The Ceiling Texture contains 2% Chrysotile asbestos and is considered a friable asbestos material.	Moderate	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Ceiling Tile	The asbestos-containing Ceiling Tile was identified within the following areas of the facility: R040A Basement Psychologist Room.	The Ceiling Tile contains 1% Amosite asbestos and 2% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Duct Insulation	The asbestos-containing Duct Insulation was identified within the following areas of the facility: Basement C003 Corridor.	Asbestos-containing Duct Insulation contains 60% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Firestop	The asbestos-containing Firestop was identified in the following areas of the facility: R010 Storage.	The Firestop contains 55% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Interior Duct Liner Panel	The asbestos-containing Interior Duct Liner Panel was identified within the following areas within the facility: 242 Activity Room.	The Interior Duct Liner Panel contain 60% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Pipe Fitting Compound	The asbestos-containing Pipe Fitting Compound was identified within the following areas of the facility: C001/C004 Corridor, R006/R007/R008 Add. Coun., R010 Storage, R012 Child Play, R013 Staff Room, R015 Meeting, R016 Storage, R017 Men's Washroom, R020 Kitchen, R021 Pop Cans, R022 Storage, R023 Library, R024A Workers C & Y, R024B S. Worker, R026 S. Worker, R027 Spch Lang Path, R029 Men's Washroom, R030 Shop, R031 Hearing Off, R032/R033 Podiatry Off, R034/R035 Podiatry Trtmt, R036 Hearing Off, R037 Clinic Off, R038 Observ Room, R046A Waiting, R046B S. Worker, R047 Reception, SB-2 Stairwell, SB-3 Stairwell, C102 Corridor, 107 Housekeeping, C127/C157/C201/C224/C244 Corridor.	The Pipe Fitting Compound contains 40-60% Chrysotile asbestos and is considered a friable asbestos material. Pipe Fitting Compound includes all mud compound located on elbows, T's, hangers, and valves located on the mechanical piping throughout the facility.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Sheet Flooring	The asbestos-containing Sheet Flooring was identified within the following areas of the facility: Basement R034/R035 Podiatry Treatment, and R036 Hearing Off.	The Sheet flooring contains 30% Chrysotile asbestos and is considered a friable asbestos material. The Sheet Flooring was found in a variety of colours and patterns throughout the facility.	High	The asbestos is present within the felt backing beneath the surface of the flooring. A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Vessel Insulation	The asbestos-containing Vessel Insulation was identified within the following areas of the facility: R049 Mechanical.	The Vessel Insulation contains 60% Chrysotile asbestos and is considered a friable asbestos material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Vinyl Floor Tile	The asbestos-containing Vinyl Floor Tile was identified within the following areas of the facility: C002/C003 Corridor, R008 Add. Coun., R012 Child Play, R013 Staff Room, R016 Storage, R051 Garbage, SB-1/SB-2/SB-3 Stairwell, 103 MH Reception, 104 Health Records and 105 Steno Pool, 109/112 PH Nurse, 119 Sen Inspect, 120 Nutritionist, 132.1 Women's Washroom, 133/133.1 Men's Washroom, 138 Storage, 144 Psychologist, 145 Hlth Nds Coord, 147 Psych Test, 150/152 Com MH Nurse, 155 Admin Assistant, S01-1/S01-2/S01-3 Stairwell, 201 Can Linen, 205 Utility, 206 Housekeeping, 230 Office, 235 Dening/Rec, 242 Activity Room, 247 Lounge, 250/253 Office, S02-1/S02-2/S02-3/S03-2 Stairwell.	The Vinyl Floor Tile insulation contains 1-6% Chrysotile asbestos and is considered a non-friable asbestos material. The Vinyl Floor Tiles were found in a variety of colours, patterns and sizes throughout the facility.	High	The asbestos is embedded in the resin of the floor tile. A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.