

Asbestos Registry Submission Form

Facility Group:	Healthcare			
Facility Group Name:	Sun Country Regional Health Authority			
Facility Name:	Carlyle Community Health Services			
Street Address:	206 Railway Avenue East			
City:	Carlyle, SK			
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir	
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager	
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca	
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377	
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email	
Date Submitted:	June 30, 2016			

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Spray-Applied Fireproofing	Asbestos-containing spray-applied fireproofing was identified within the exterior wall cavities and the underside of roof decking throughout the South Garage portion of the facility. In addition, similar material was identified on the interior side of the perimeter metal wall cladding and the underside of the exterior roof decking in the Front Public Health Office Area.	The spray-applied fireproofing contains Crocidolite Asbestos and is considered a friable asbestos material.	Moderate / High Access is restricted to the South Garage until abatement has been completed. The material in the Public Health Office is enclosed by physical barriers.	Restricted access to the walls / ceiling space of the Public Health Office to competent persons trained in asbestos abatement techniques. Restrict all access to the South Garage.