

# Asbestos Registry Submission Form

<b>Facility Group:</b>	Healthcare			
<b>Facility Group Name:</b>	Sun Country Regional Health Authority			
<b>Facility Name:</b>	Estevan Regional Nursing Home			
<b>Street Address:</b>	1921 Wellock Road			
<b>City:</b>	Estevan, SK			
<b>Primary Contact Name:</b>	Sam Baison	<b>Secondary Contact Name:</b>	John Megenbir	
<b>Primary Contact Title:</b>	Director - Physical Plant	<b>Secondary Contact Title:</b>	Maintenance Manager	
<b>Primary Contact Email Address:</b>	Samuel.Baison@schr.sk.ca	<b>Secondary Contact Email Address:</b>	John.Megenbir@schr.sk.ca	
<b>Primary Contact Telephone:</b>	306-842-8304	<b>Secondary Contact Telephone:</b>	306-842-8377	
<b>Primary Contact Preferred Method:</b>	Email	<b>Secondary Contact Preferred Method:</b>	Email	
<b>Date Submitted:</b>	June 30, 2016			

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Asbestos Debris	Located throughout the Kitchen Crawlspace.	Loose asbestos debris, a product of deteriorating mechanical insulation located throughout the Crawlspace. The debris was found to contain 70% chrysotile asbestos and is considered to be friable.	Low. Restricted to Maintenance Staff equipped with proper PPE.	Crawlspace was abated in November 2014 by APEC.
Pipefitting Compound	Asbestos pipefitting compound was identified in the Crawlspace and various areas of the Basement including: the Boiler Room, Stairwell, Corridor, Laundry Room, Maintenance Office, Storage Room and Washrooms . All pipefitting compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The pipefitting compound contains 15 - 75% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass. Access is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand. All accessible pipefitting compound was repaired / removed by Associated Asbestos Abatement in June 2013.
Boiler Breaching	Asbestos boiler breaching was found in Boiler Room. All breaching shall be considered asbestos-containing until the material is determined to be asbestos free.	The breaching insulation contains 50% Chrysotile / Amosite Asbestos and is considered a friable asbestos material.	Low. Access to this area is restricted to Maintenance personnel.	A friable product is one that is easily crumbled by hand pressure.