

Asbestos Registry Submission Form

Facility Group:	Healthcare		
Facility Group Name:	Sun Country Regional Health Authority		
Facility Name:	Lampman Health Centre		
Street Address:	309 - 2nd Avenue		
City:	Lampman, SK		
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email
Date Submitted:	June 30, 2016		

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Sheet Vinyl Floor	Asbestos-containing sheet vinyl floor was identified within the Ladies Changeroom / Washroom.	The sheet vinyl floor contains 30% Chrysotile Asbestos and is considered a friable asbestos material. The flooring is identifiable by the large brown square pattern.	Low. The asbestos is present within the felt backing beneath the surface of the flooring.	Ensure the facing surface of the sheet flooring is maintained in good repair.
Heat Deflector Shield	Asbestos heat deflector shield material was found in the light fixtures located in the following locations: Ward Washrooms #2-5, Ward 2 Washroom, Ladies Changeroom/Washroom and the X-ray Room. All heat shield material shall be considered asbestos-containing until the material is determined to be asbestos free.	The heat deflector shield material contains 70% Chrysotile Asbestos and is considered a friable asbestos material. The heat deflector shields are located in the old Incandescent light fixtures in the rooms identified.	Low. Access to this area is restricted to Maintenance personnel.	A friable product is one that is easily crumbled by hand pressure.
Mud Compound on Roof Drain Line	Asbestos mud compound was identified on the roof drain cones throughout the Main Floor Ceiling Space. All mud compound on roof drain lines shall be considered asbestos-containing until the material is determined to be asbestos free.	The roof drain mud compound contains 75% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Located within Ceiling Space. Access is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand. Roof drain cone mud was removed in the Kitchen, the Day Room, the Housekeeping Room and Emergency in November 2014 by APEC.