

Asbestos Registry Submission Form

Facility Group:	Healthcare			
Facility Group Name:	Sun Country Regional Health Authority			
Facility Name:	Pangman Health Centre			
Street Address:	211 Keeler Street			
City:	Pangman, SK			
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir	
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager	
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca	
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377	
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email	
Date Submitted:	June 30, 2016			

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Pipefitting Compound	Asbestos pipefitting compound was identified throughout the Crawlspace and Basement Stairwell SB1-1. All pipefitting compound shall be considered asbestos-containing until the material is determined to be asbestos free.	The pipefitting compound contains 30 - 60% Chrysotile Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass. Access is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand. All accessible pipefitting compound was repaired / removed by APEC in November 2014.
Lineal Pipe Insulation	Asbestos lineal pipe insulation was identified in various areas of the Crawlspace. All lineal pipe insulation shall be considered asbestos-containing until the material is determined to be asbestos free.	The lineal pipe insulation contains 60 - 70% Chrysotile and Amosite Asbestos. The insulation is considered a friable material.	Low. Enclosed with canvass. Access is restricted to maintenance personnel.	A friable product is one that is easily crumbled by hand. All accessible lineal pipe insulation was repaired / removed by APEC in November 2014.