

Asbestos Registry Submission Form

Facility Group:	Healthcare		
Facility Group Name:	Sun Country Regional Health Authority		
Facility Name:	Redvers Health Centre		
Street Address:	18 Eichorst Street		
City:	Redvers, SK		
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email
Date Submitted:	July 19, 2017		

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Drywall Mud Compound	Asbestos Containing Drywall Mud Compound was identified in a compilation sample taken from the water softner room. Asbestos containing drywall mud compound is mostly located on joints, tape seams, and screw holes. It is advised that all drywall mud compound in the facility be considered asbestos containing until sampling proves otherwise.	Drywall Mud Compound contains 1-5% Chrysotile and is considered a friable product.	Low. The asbestos is imbedded in the mud at joints, tape seams, and screw holes.	A friable product is one that is easily crumbled by hand pressure.