

# Asbestos Registry Submission Form

<b>Facility Group:</b>	Healthcare			
<b>Facility Group Name:</b>	Sun Country Regional Health Authority			
<b>Facility Name:</b>	Weyburn Regional Maintenance Office			
<b>Street Address:</b>	Saskatchewan Drive			
<b>City:</b>	Weyburn, SK			
<b>Primary Contact Name:</b>	Sam Baison	<b>Secondary Contact Name:</b>	John Megenbir	
<b>Primary Contact Title:</b>	Director - Physical Plant	<b>Secondary Contact Title:</b>	Maintenance Manager	
<b>Primary Contact Email Address:</b>	Samuel.Baison@schr.sk.ca	<b>Secondary Contact Email Address:</b>	John.Megenbir@schr.sk.ca	
<b>Primary Contact Telephone:</b>	306-842-8304	<b>Secondary Contact Telephone:</b>	306-842-8377	
<b>Primary Contact Preferred Method:</b>	Email	<b>Secondary Contact Preferred Method:</b>	Email	
<b>Date Submitted:</b>	July 19, 2017			

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Vinyl Asbestos Tile	Vinyl asbestos floor tile was identified in the following areas: the Carpentry Shop (North), Paint Shop, Paint Storage, Paint Booth and the Stairwell Landing. All 9" x 9" vinyl floor tile throughout the facility shall be considered asbestos-containing until the material is determined to be asbestos free.	The Vinyl Floor Tile contains 1-5% Chrysotile Asbestos and is considered a non-friable asbestos material. The floor tiles are in the form of 9"x9" blue and beige vinyl tiles within the facility.	Low. The asbestos is imbedded in the floor tile resin.	A non-friable product is one that can not be crumbled or reduced to powder or smaller fragments by hand pressure.