

Type of Facility:	Health Care Facility		
Facility Group Name:	Sun Country Health Authority		
Facility Name:	Weyburn Regional Maintenance Office		
Location:	Saskatchewan Drive, Weyburn, SK		
Date of Submission:	31-Dec-18		
Primary Contact Name:	Marlon Milbrandt	Secondary Contact Name:	Barry Brumfield
Primary Contact Title:	Director - Building Services Rural	Secondary Contact Title:	Building Services Manager
Primary Contact Email Address:	Marlon.Milbrandt@saskhealthauthority.ca	Secondary Contact Email Address:	Barry.Brumfield@saskhealthauthority.ca
Primary Contact Telephone:	(306) 786-0416	Secondary Contact Telephone:	(306) 842-8316
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Vinyl Floor Tile	The asbestos-containing Vinyl Floor Tile was identified within the following areas of the facility: Rm 4 Carpentry Shop - North, Rm 5 Paint Shop, Rm 6 Paint Storage Room, Rm 7 Paint Booth and Stairwell Landing.	The Vinyl Floor Tile contains 1-5% Chrysotile asbestos and is considered a non-friable asbestos material. The floor tiles are found in a variety of colours and patterns throughout the facility.	Low	The asbestos is embedded in the resin of the floor tile. Although the floor tile is labelled high accessibility to the public, there is no hazard. A non-friable product is one that cannot be crumbled or reduced to powder or smaller fragments by hand pressure.