

Type of Facility:	Health Care Facility		
Facility Group Name:	Sun Country Health Authority		
Facility Name:	Lampman Health Centre		
Location:	311 - 2nd Avenue, Lampman, SK		
Date of Submission:	20-Dec-19		
Primary Contact Name:	John Megenbir	Secondary Contact Name:	Marlon Milbrandt
Primary Contact Title:	Building Services Manager	Secondary Contact Title:	Director - Building Services Rural
Primary Contact Email Address:	John.Megenbir@saskhealthauthority.ca	Secondary Contact Email Address:	Marlon.Milbrandt@saskhealthauthority.ca
Primary Contact Telephone:	306-842-8377	Secondary Contact Telephone:	(306) 786-0416
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email

1. Type of Asbestos Containing Material [ACM]	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Heat Deflector Shield	The asbestos-containing Heat Deflector Shields were identified within the following areas within the facility: Ladies Changeroom/Washroom, Ward 2 Washroom, 02-05 Ward Washroom's and X-Ray Room.	The Heat Deflector Shields contain 70% Chrysotile asbestos are considered a friable asbestos material. The Heat Shield is located directly above the light bulbs within the light fixture to prevent overheating of building materials above.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure. Ensure the globe of the light fixture is in place to enclose/conceal the Heat Deflector Shield.
Mud Compound	The asbestos-containing Mud Compound was identified within the following areas of facility: Main Floor Storage Room, Housekeeping Room Adj. Ladies Change Room, Ladies Change Room, Kitchen, Corridor Adj. Emergency Room, 02-05 Ward Rooms, Lab, and X-Ray Film Development Room.	The Mud Compound contains 75% Chrysotile asbestos and is considered a friable material.	Low	A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.
Sheet Flooring	The asbestos-containing Sheet Flooring was identified within the following areas of the facility: Main Floor Ladies Change Room/Washroom.	The Sheet flooring contains 30% Chrysotile asbestos and is considered a friable asbestos material. The sheet flooring was found in a variety of colours and patterns throughout the facility.	High	The asbestos is present within the felt backing beneath the surface of the flooring. A friable product is one that can be crumbled or reduced to powder or smaller fragments by hand pressure.