

Asbestos Registry Submission Form

Facility Group:	Healthcare		
Facility Group Name:	Sun Country Regional Health Authority		
Facility Name:	Weyburn Regional Maintenance Office		
Street Address:	Saskatchewan Drive		
City:	Weyburn, SK		
Primary Contact Name:	Sam Baison	Secondary Contact Name:	John Megenbir
Primary Contact Title:	Director - Physical Plant	Secondary Contact Title:	Maintenance Manager
Primary Contact Email Address:	Samuel.Baison@schr.sk.ca	Secondary Contact Email Address:	John.Megenbir@schr.sk.ca
Primary Contact Telephone:	306-842-8304	Secondary Contact Telephone:	306-842-8377
Primary Contact Preferred Method:	Email	Secondary Contact Preferred Method:	Email
Date Submitted:	June 30, 2016		

1. Type of Asbestos-Containing Material (ACM) (or groups of ACM)	2. Location in Facility	3. Characteristics	4. Accessibility	5. Comments (Optional)
Vinyl Asbestos Tile	Vinyl asbestos floor tile was identified in the following areas: the Carpentry Shop (North), Paint Shop, Paint Storage, Paint Booth and the Stairwell Landing. All 9" x 9" vinyl floor tile throughout the facility shall be considered asbestos-containing until the material is determined to be asbestos free.	The Vinyl Floor Tile contains 1-5% Chrysotile Asbestos and is considered a non-friable asbestos material. The floor tiles are in the form of 9"x9" blue and beige vinyl tiles within the facility.	Low. The asbestos is imbedded in the floor tile resin.	A non-friable product is one that can not be crumbled or reduced to powder or smaller fragments by hand pressure.